


Note: Make sure to place 5 jumpers after programming MCU and removing PICFlash connector in order for MCU to be able to execute the program. For more details refer to the PICFlash programmer manual.



**PICFlash CONNECTOR**